

University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To:Mehmood-ul-Hassan, G.M
DMIX Concrete Lahore.
Project: Lahore School of Economics.Our Ref. No. CL/CED/7753Dated:08-04-19

Your Ref. No. Nil Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

28-03-19

Specimens received on:

Tested on:

03-04-19

19 in dry/wet condition

_		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
ŝr. No	Mark*	M	/et W	/eight	(in)	(lbs./gms)	X-Section	load	Stress	Remarks
0)			(gms)				(Sq. in)	(Tons/lbs)	(Psi)	
1	Slab	9	3	2019	6Diax12	14	28.28	98	7770	Non Engraved
2	Slab	9	3	2019	6Diax12	14	28.28	98	7770	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)

Director/Dy. Director Concrete Laboratory

8337 Dr. Umbreen



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Engr. Hammad Hassan Sindhu, RE Dr. Ad EA Consulting (Pvt) Ltd. Project:Const. of St. Through Provi.of PCC & Gully Grat. at Eshwar Nagar Ward No.01 (PP-156) Our Ref. No. CL/CED/ 7754 Dated: 08-04-19

Your Ref. No. RE/EA/TEPA-LDA/LHR/1332 Dated: 12-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

28-03-19

Specimens received on:

Tested on:

28-03-19 in dry/wet condition

Ultimate Ultimate Casting Date* Size Weight Area of Š Х-/Wet Weight Mark* (in) (lbs./gms) load Stress Remarks Section ູ່ດີ (gms) (Sq. in) (Tons/lbs) (Psi) T-22 17 2019 12.8 1 1 6Diax12 28.28 50 3970 Non Engraved End ------------------------3 4 5 6 7 8 9 10 11 12 13 14 15 16

Results can also be seen on website <u>http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6</u>

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as compressive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)

Director/Dy. Director Concrete Laboratory

8338 Dr. Aqsa



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Engr. Hammad Hassan Sindhu, RE EA Consulting (Pvt) Ltd.

Project: Provision of Tuff Tiles at Hussain Abad along Acad.Road Lhr. Cantt. (PP-156) NA-125

 Our Ref. No. CL/CED/
 7755
 Dated:
 08-04-19

Your Ref. No. RE/EA/TEPA-LDA/LHR/1324 Dated: 12-03-19

COMPRESSION TEST REPORT

Conc	rete Cubes/Concre	te Cy	ylind	lers/Bric	ks/Cores/Tuff	Tiles/Paver	S			
Spec	imens received on:	2	28-03-19		Tested on:		28-03- 19 in dry/wet condition			
Sr. No.	Mark*	Ca /M	sting Vet W	∣ Date* √eight	Size (in)	Weight A		Ultimate load	Ultimate Stress	Remarks
		(gms)					(Sq. in)	(Tons/lbs)	(Psi)	
1	T-22	17	1	2019	6Diax12	12.5	28.28	60	4760	Non Engraved
End										
3										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										
Resu	Its can also be seen	on w	ebsit	te <u>http://</u>	www.uet.edu.pl	k/faculties/fac	cultiesinfo/	department?RI	D=testing re	eports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)

Director/Dy. Director Concrete Laboratory

8338 Dr. Aqsa



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Bilal Ahmed, Project Manager

8345 Dr. Qasim Khan

National Technical Services, Suite#1102,11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7756	Dated:	08-04-19

Your Ref. No. Nil Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-

29-03-19 in dry/wet condition

-		r								
		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No	Mark*	M	/Wet Weight		(in)	(lbs./gms)	X- Section	load	Stress	Remarks
0)			(gms)				(Sq. in)	(Tons/lbs)	(Psi)	
1		17	2	2019	6x6x6	8.2	36	51	3180	Non Engraved
2		17	2	2019	6x6x6	8.2	36	60	3740	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

Bilal Ahmed, Project Manager To:

8345

Dr. Qasim Khan National Technical Services, Suite#1102, 11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7757	Dated:	08-04-19

Your Ref. No. Nil Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-19 in dry/wet condition

Sr. No.	Mark*	Casting Date*		Size (in)	Weight (lbs./gms)	Area of X- Section	Ultimate load	Ultimate Stress	Remarks	
			(gm	is)			(Sq. in)	(Tons/lbs)	(Psi)	
1		27	2	2019	6x6x6	8.4	36	60	3740	Non Engraved
2		27	2	2019	6x6x6	8	36	74	4610	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Bilal Ahmed, Project Manager

8345 Dr. Qasim Khan

National Technical Services, Suite#1102,11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7758	Dated:	08-04-19	
Your Ref. No.	Nil	Dated:	28-03-19	

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-19

-19 in dry/wet condition

ġ		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
ŝr. No	Mark*	/M	/et W	/eight	(in)	(lbs./gms)	X-Section	load	Stress	Remarks
0)			(gms)				(Sq. in)	(Tons/lbs)	(Psi)	
1		22	2	2019	6x6x6	8.4	36	44	2740	Non Engraved
2		22	2	2019	6x6x6	8.2	36	50	3120	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

Bilal Ahmed, Project Manager To:

8345 Dr. Qasim Khan

National Technical Services, Suite#1102, 11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7759	Dated:	08-04-19
			~~ ~~ ~~

Dated: Your Ref. No. Nil 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-19 in dry/wet condition

r	I	-					1			
		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No	Mark*	M	/Wet Weight		(in)	(lbs./gms)	X- Section	load	Stress	Remarks
			(gms)				(Sq. in)	(Tons/lbs)	(Psi)	
1		3	3	2019	6x6x6	8.2	36	55	3430	Non Engraved
2		3	3	2019	6x6x6	8.2	36	68	4240	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Bilal Ahmed, Project Manager

8345 Dr. Qasim Khan

National Technical Services, Suite#1102,11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7760	Dated:	08-04-19
Your Ref. No.	Nil	Dated:	28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03

29-03-19 in dry/wet condition

-										
÷		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
ŝr. No	Mark*	N	/Wet Weight		(in)	(lbs./gms)	X-Section	load	Stress	Remarks
0,			(gms)				(Sq. in)	(Tons/lbs)	(Psi)	
1		4	2	2019	6x6x6	8.6	36	66	4110	Non Engraved
2		4	2	2019	6x6x6	8.4	36	57	3550	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as compressive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: **Bilal Ahmed, Project Manager**

8345 Dr. Qasim Khan

National Technical Services, Suite#1102, 11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7761	Dated:	08-04-19
Your Ref. No.	Nil	Dated:	28-03-19

Tested on:

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19

29-03-19 in dry/wet condition

					0.				1.11.0	
ġ		Ca	sting	Date*	Size	weight	Area of	Ultimate	Ultimate	
Sr. No	Mark*	/Wet Weight		(in)	(lbs./gms)	X- Section	load	Stress	Remarks	
			(gm	s)			(Sq. in)	(Tons/lbs)	(Psi)	
1		28	1	2019	6x6x6	8	36	37	2310	Non Engraved
2		28	1	2019	6x6x6	8.2	36	58	3610	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

Bilal Ahmed, Project Manager To:

8345 Dr. Qasim Khan

National Technical Services, Suite#1102, 11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7762	Dated:	08-04-19

Your Ref. No. Nil Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-19 in dry/wet condition

Sr. No.	Mark*	Casting Date* /Wet Weight		Size (in)	Weight (lbs./gms)	Area of X- Section	Ultimate load	Ultimate Stress	Remarks	
			(gn	ıs)			(Sq. in)	(Tons/lbs)	(Psi)	
1		9	2	2019	6x6x6	8.2	36	45	2800	Non Engraved
2		9	2	2019	6x6x6	8.2	36	56	3490	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Bilal Ahmed, Project Manager

8345 Dr. Qasim Khan

National Technical Services, Suite#1102, 11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7763	Dated:	08-04-19

Your Ref. No. Nil Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-19 in dry/wet condition

	Mark*	Casting Date* /Wet Weight			Size	Weight	Area of	Ultimate	Ultimate	
Sr. Z					(in)	(lbs./gms)	X- Section	load	Stress	Remarks
			(gms)				(Sq. in)	(Tons/lbs)	(Psi)	
1		16 2 2019		2019	6x6x6	8.2	36	26	1620	Engraved
2		16	2	2019	6x6x6	8.2	36	54	3360	Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

Bilal Ahmed, Project Manager To:

8345 Dr. Qasim Khan

National Technical Services, Suite#1102, 11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7764	Dated:	08-04-19

Your Ref. No. Nil Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-19 in dry/wet condition

Sr. No.	Mark*	Casting Date* /Wet Weight (gms)		Casting Date* /Wet Weight (ams)		Size (in)	Weight (lbs./gms)	Area of X- Section (Sq. in)	Ultimate load (Tons/lbs)	Ultimate Stress (Psi)	Remarks
1		15	2	2019	6x6x6	9.2	36	58	3610	Non Engraved	
2		15	2	2019	6x6x6	8.6	36	63	3920	Non Engraved	
End											
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											
16											

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

Bilal Ahmed, Project Manager To:

8345 Dr. Qasim Khan

National Technical Services, Suite#1102, 11th Floor, Chapal Plaza, Hasrat Mohani Road, Karachi. Project: Raised of Boundary Wall at Machike Shell Terminal. (Foundation, s Footing and Column)

Our Ref. No. CL/CED/	7765	Dated:	08-04-19

Your Ref. No. Nil Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19 Tested on:

29-03-19 in dry/wet condition

Sr. No.	Mark*	Casting Date* /Wet Weight (gms)		Size (in)	Weight (Ibs./gms)	Area of X- Section (Sq. in)	Ultimate load (Tons/lbs)	Ultimate Stress (Psi)	Remarks	
1		12	2	2019	6x6x6	8.2	36	68	4240	Non Engraved
2		12	2	2019	6x6x6	8.4	36	62	3860	Non Engraved
End										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to

be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

> 8346 Dr. Umbreen

To: Mr. Usman Ali, Project Manager Mukhtar Sons Construction Pvt. Ltd.

Project: Naveena Apartments, 35-C, Gulberg III, Lahore.

Our Ref. No. CL/CED/	7766	Dated:	08-04-19
Your Ref. No.	Nil	Dated:	28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19

Tested on:

03-04-19 in dry/wet condition

r										
		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
r. No	Mark*	M	/et W	/eight	(in)	(lbs./gms)	X-Section	load	Stress	Remarks
S			(gms)				(Sq. in)	(Tons/lbs)	(Psi)	
1	G.F. Slab Pour-2nd	14	3	2019	6Diax12	14.2	28.28	67	5310	Non Engraved
2	G.F. Slab Pour-2nd	14	3	2019	6Diax12	14	28.28	63	5000	Non Engraved
3	G.F. Slab Pour-2nd	14	3	2019	6Diax12	14	28.28	69	5470	Non Engraved
End										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as compressive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

> 8346 Dr. Umbreen

To: Mr. Usman Ali, Project Manager Mukhtar Sons Construction Pvt. Ltd.

Project: Naveena Apartments, 35-C, Gulberg III, Lahore.

Our Ref. No. CL/CED/	7767	Dated:	08-04-19
Your Ref. No.	Nil	Dated:	28-03-19

COMPRESSION TEST REPORT

Tested on:

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

28-03-19

03-04-19 in dry/wet condition

·										
		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No	Mark*	///	/et W	/eight	(in)	(lbs./gms)	X- Section	load	Stress	Remarks
0,			(gm	is)			(Sq. in)	(Tons/lbs)	(Psi)	
1	G.F. Slab Pour-1st	23	2	2019	6Diax12	14.6	28.28	73	5790	Non Engraved
2	G.F. Slab Pour-1st	23	2	2019	6Diax12	14.4	28.28	73	5790	Non Engraved
3	G.F. Slab Pour-1st	23	2	2019	6Diax12	14.4	28.28	69	5470	Non Engraved
End										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website <u>http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6</u>

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as compressive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Mr. Irfan Ali, Construction Manager

8347 Dr. Umbreen

MEDEQUIPS Pvt. Ltd. 33-0 Project:	C. F.C.C Comme	rcial Plot Gulbe	rg II, Lahore.
Our Ref. No. CL/CED/	7768	Dated:	08-04-19

our Ref. No.	Nil	Dated:	29-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

Υ

29-03-19 Tested on:

03-04-19 in dry/wet condition

			Casting I		Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No	Mark*	/W	/et W	/eight	(in)	(lbs./gms)	X- Section	load	Stress	Remarks	
			(gm	is)			(Sq. in)	(Tons/lbs)	(Psi)		
1	Cols. 2nd Floor	18	2	2019	6Diax12	14	28.28	49	3890	Engraved	
2	Cols. 2nd Floor	18	2	2019	6Diax12	13.6	28.28	43	3410	Engraved	
3	Cols. 2nd Floor	18	2	2019	6Diax12	13.8	28.28	57	4520	Engraved	
4	Slab 2nd Floor	21	3	2019	6Diax12	13	28.28	33	2620	Engraved	
5	Slab 2nd Floor	21	3	2019	6Diax12	13.2	28.28	35	2780	Engraved	
6	Slab 2nd Floor	21	3	2019	6Diax12	13	28.28	39	3090	Engraved	
End											
8											
9											
10											
11											
12											
13											
14											
15											
16											

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Muhammad Aftab, Asstt. to General Manager Banu Mukhtar Contracting Pvt. Ltd. Project: INTERLOOP GREEN DENIM FACTOR

Our Ref. No. CL/CED/	7769	Dated:	08-04-19
Your Ref. No.	BMC/INTERLOOP/004	Dated:	29-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

29-03-19

Tested on:

03-04-19 in dry/wet condition

		•								
		Casting Date*		Size	Weight	Area of	Ultimate	Ultimate		
Sr. No	Mark*	M	/et V	/eight	(in)	(lbs./gms)	X- Section	load	Stress	Remarks
0,			(gm	ıs)			(Sq. in)	(Tons/lbs)	(Psi)	
1	Roof Slab+Beam	27	2	2019	6x6x6	8.6	36	63	3920	Non Engraved
2	Roof Slab+Beam	27	2	2019	6x6x6	8.6	36	77	4800	Non Engraved
3	Roof Slab+Beam	27	2	2019	6x6x6	8.6	36	88	5480	Non Engraved
4	Roof Slab+Beam	27	2	2019	6x6x6	8.8	36	86	5360	Non Engraved
END										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as compressive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)

Director/Dy. Director Concrete Laboratory

8349 Dr. Umbreen



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: **Sub Divisional Officer**

8354 Dr. Umbreen

Buildings Sub Division No.12, Lahore. Project:Constt. of Office Complex of Food Directorate Divi. Food Office Lhr. & DFC, Office Laho									
Our Ref. No. CL/CED/	7770	Dated:	08-04-19						

Your Ref. No. 234/SDO 12th Dated: 28-03-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

29-03-19 Tested on:

03-04-19 in dry/wet condition

		1			1					
ġ		Cas	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No	Mark*	/W	et W	eight	(in)	(lbs./gms)	X- Section	load	Stress	Remarks
			(gm	s)			(Sq. in)	(Tons/lbs)	(Psi)	
1	Slab 3rd Floor	28	2	2019	6Diax12	13.4	28.28	57	4520	Non Engraved
2	Slab 3rd Floor	28	2	2019	6Diax12	13.4	28.28	43	3410	Non Engraved
END										
4										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to

be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

8355

Engr. Asif Jah, Executive Engineer Tamirat To: Dr. Umbreen Anjuman Himayat-i-Islam, 119 Multan Road Lahore. Project: Remaining Works of Constt. of D-Plaza at Al-Mumtaz Road Dar-ul-Shafqat for Boys, Lahore. Our Ref. No. CL/CED/ 7771 Dated: 08-04-19 Your Ref. No. Tm-715 Dated: 28-03-19 COMPRESSION TEST REPORT Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers 29-03-19 Specimens received on: Tested on: 03-04-19 in dry/wet condition Size Ultimate Ultimate Casting Date* Weight Area of Š Х-/Wet Weight Remarks Mark* (in) (lbs./gms) load Stress Section ຈັ (Sq. in) (Tons/lbs) (gms) (Psi) 28 2 2019 6x6x6 4420 Non Engraved 1 Slab 8.3 36 71 2 Slab 28 2 2019 6x6x6 8.4 36 4300 Non Engraved 69 END ------------------------------4 5 6 7 8 9 10 11 12 13 14 15 16

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)