

University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Project Manager SM Imran House

8556 Dr. Rizwan Azam

Project: SM Imran House, (Canopies Top Roof)

 Our Ref. No. CL/CED/
 7989
 Dated:
 03-05-19

 Your Ref. No.
 M4/H2/LCHS/18
 Dated:
 30-04-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

30-**04**-19 Tested on:

0

03-05-19 in dry/wet condition

	Mark*	Casting Date*		Size	Weight	Area of	Ultimate	Ultimate		
Sr. No.		/Wet Weight			(in)	(lbs./gms)	X-Section	load	Stress	Remarks
0)			(gm	s)			(Sq. in)	(Tons/lbs)	(Psi)	
1		14	4	2019	6Diax12	14	28.28	63	5000	Non Engraved
2		14	4	2019	6Diax12	14.2	28.28	39	3090	Non Engraved
3		14	4	2019	6Diax12	14	28.28	61	4840	Non Engraved
End										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix

proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

8556 Dr. Rizwan To: Project Manager Azam **SM Imran House** Project: SM Imran House, (Firefighting Tank Slab) Our Ref. No. CL/CED/ 7990 Dated: 03-05-19

Your Ref. No. M4/H2/LCHS/16 Dated: 30-04-19 COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

Tested on: 30-04-19

03-05-19 in dry/wet condition

	Mark*	Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No.		M	/et W	/eight	(in)	(lbs./gms)	X- Section	load	Stress	Remarks
		(gms)					(Sq. in)	(Tons/lbs)	(Psi)	
1		2	4	2019	6Diax12	14.1	28.28	35	2780	Non Engraved
2		2	4	2019	6Diax12	14	28.28	67	5310	Non Engraved
3		2	4	2019	6Diax12	14	28.28	41	3250	Non Engraved
End										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: Project Manager

8556 Dr. Rizwan Azam

SM Imran House

Project: SM Imran House, (Boundary Wall, Raffey House Side)

Our Ref. No. CL/CED/	7991	Dated:	03-05-19
Your Ref. No.	M4/H2/LCHS/17	Dated:	30-04-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

30-**04**-19 Tested on:

03-05-19 in dry/wet condition

1		1								
		Ca	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No.	Mark*	M	/et W	/eight	(in)	(lbs./gms)	X- Section	load	Stress	Remarks
		(gms)					(Sq. in)	(Tons/lbs)	(Psi)	
1		8	4	2019	6Diax12	14	28.28	29	2300	Non Engraved
2		8	4	2019	6Diax12	14.2	28.28	39	3090	Non Engraved
3		8	4	2019	6Diax12	13.8	28.28	27	2140	Non Engraved
End										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

Major (Muhammad Farhan Khan) Project Officer. (Contractor, M/S Trust Developers & To: Constt. Pvt. Ltd.)

19 Engineers Battalion (Chaghai Sappers) Sheikhupura Camp C/O Signal Centre (FWO Chaklala) Project: Rehabilitation Works at Kot Abdul Malik Bridge.(South Bound) Motorway (M-2).

Our Ref. No. CL/CED/	7992	Dated:	03-05-19
Your Ref. No.	607/SDO B&R/General	Dated:	30-04-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

02-05-19

Tested on:

03-05-19 in dry/wet condition

8570

Azam

Dr. Rizwan

Sr. No.	Mark*		Casting Date* /Wet Weight (gms)		Size (in)	Weight (Ibs./gms)	Area of X- Section (Sq. in)	Ultimate load (Tons/lbs)	Ultimate Stress (Psi)	Remarks
1		30	3	2019	6Diax12	13	28.28	83	6580	Non Engraved
2		30	3	2019	6Diax12	13	28.28	104	8240	Non Engraved
3		30	3	2019	6Diax12	13.2	28.28	98	7770	Non Engraved
End										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as compressive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

To: (Aamir Shehzad Mughal), Site Engineer

8521 Engr. A. Rehman

BKRY Lahore. 30-KM Ferozpur Road, Lahore.

Project: Construction of BKRY 30-KM Ferozpur Road, Lahore. (Slab Block-A)

Our Ref. No. CL/CED/	7993	Dated:	03-05-19
Your Ref. No.	TBL/19/010	Dated:	24-04-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

24-**04**-19 Tested on: 29-04-19 in dry/wet condition

Casting Date* Size Weight Area of Ultimate Ultimate o Z Χ-Mark* /Wet Weight (in) (lbs./gms) load Stress Remarks Section ທັ (Tons/lbs) (gms) (Sq. in) (Psi) 1 Slab & Beams 28 3 2019 6Diax12 13.6 28.28 51 4040 Non Engraved 28 2 3 2019 6Diax12 Slab & Beams 14.4 28.28 48 3810 Non Engraved 3 RCC Lift Wall 17 4 2019 6Diax12 14 28.28 17 1350 Non Engraved 4 RCC Lift Wall 17 4 2019 6Diax12 14 28.28 16.75 1330 Non Engraved End ---___ ___ ---------------____ ____ 6 7 8 9 10 11 12 13 14 15 16

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

Mr. Imtiaz Ali. Lead QA&QC To:

8508 Dr. Umbreen

PCL Project, DESCON Engineering Pvt. Ltd.

Project: 7700 TPD-Pioneer Cement Project (CP10055), "Cooler Laboratory Room Slab, E.L:+2.800m"

Our Ref. No. CL/CED/	7994	Dated:	03-05-19
Your Ref. No.	Nil	Dated:	23-04-19

COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

Tested on: 23-04-19

03-05-19 in dry/wet condition

Ir		1				I	[]
		Casting D		Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No.	Mark*	/Wet Weight			(in)	(lbs./gms)	X- Section	load	Stress	Remarks
		(gms)				(Sq. in)	(Tons/lbs)	(Psi)		
1	C30	12	4	2019	6x6x6	8.6	36	77	4800	Non Engraved
2	C30	12	4	2019	6x6x6	8.4	36	98	6100	Non Engraved
3	C30	12	4	2019	6x6x6	8.6	36	86	5360	Non Engraved
End										
5										
6										
7										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)



University of Engineering and Technology, Lahore Phone Nos. 042-99029202, 042-99029217

> 8513 Engr. A. Rehman

To: General Manager (Projects) AS Enterprises (Engineers & Contractors)

Project:Style Textile Mills. (Consultants, AA Associates)

Our Ref. No. CL/CED/	7995	Dated:	03-05-19
Your Ref. No.	ASE/STM/001	Dated:	23-04-19

COMPRESSION TEST REPORT

Tested on:

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:

23-04-19

03-05-

03-05-19 in dry/wet condition

		Са	sting	Date*	Size	Weight	Area of	Ultimate	Ultimate	
Sr. No.	Mark*	M	/et W	/eight	(in)	(lbs./gms)	X- Section	load	Stress	Remarks
		(gms)					(Sq. in)	(Tons/lbs)	(Psi)	
1	C-20, Col. Footing	15	4	2019	6x6x6	8.4	36	81	5040	Non Engraved
2	C-20, Col. Footing	15	4	2019	6x6x6	8.4	36	92	5730	Non Engraved
3	C-20, Col. Footing	15	4	2019	6x6x6	8.2	36	84	5230	Non Engraved
4	C-30, Stub Col.	15	4	2019	6x6x6	8.2	36	74	4610	Non Engraved
5	C-30, Stub Col.	15	4	2019	6x6x6	8.2	36	88	5480	Non Engraved
6	C-30, Stub Col.	15	4	2019	6x6x6	8	36	84	5230	Non Engraved
End										
8										
9										
10										
11										
12										
13										
14										
15										
16										

Results can also be seen on website http://www.uet.edu.pk/faculties/facultiesinfo/department?RID=testing_reports&id=6

* as engraved on the specimens (if any)

** BS3921 requires average of ten clay brick samples for crushing strength and water absorption

*** BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

**** ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as compressive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients). The test results are recommended to be interpreted in the light of above factors by the engineer.

supervisor(lab)